


Airmix RH measurement climate computer



	Items	Unit	Group	Factor	Ash	Min	Max	Average	Line
<input checked="" type="checkbox"/>	RH	%	Dept. 5	1	->	75	90	86	75
<input checked="" type="checkbox"/>	Outside temperature	*C	Weather	1	<-	4.8	11.0	7.2	10.7
<input checked="" type="checkbox"/>	Greenhouse temperature	*C	Dept. 5	1	<-	18.8	25.5	21.0	24.9
<input checked="" type="checkbox"/>	Greenhouse temperature, above screen	*C	Above screen dept. 5	1	<-	7.1	22.0	12.8	17.0
<input checked="" type="checkbox"/>	Energy screen	%	Dept. 5 Engery screen	1	->	0	100	61	0
<input checked="" type="checkbox"/>	Valve angle	%	Dept. 5+6	1	->	2.8	100.6	23.9	100.6
<input checked="" type="checkbox"/>	Black out screen	%	Dept. 5 black out screen	1	->	0	100	76	100